

Construction Report no.3



We inspected a prototype made based on the shachigawara clay mold confirmed with half body in September.





Similarly, we inspected prototypes of tiles baked based on the gatou confirmed in September.



Construction Report no.3




The timbers that started marking and processing.
【upper photo: timbers for roof truss, lower photo: timbers for rafter】



Construction Report no.3



We checked how the timbers that started processing were finished with chouna (adze).



Construction Report no.3



We checked the processing status of the joints.





Even if the material has passed the inspection, cracks or twists may be found during the drying period or at the beginning of processing, in which case a new replacement material must be secured. It is the difficulty of treating a natural material.



We also check the quality of the replacement material, and for materials with a high moisture content, we secure a storage place indoors and dry it.